

FACILITY ACCESSIBILITY EVALUATION

ESS 363 Adapted Physical Activity

DIRECTIONS: Use this basic checklist as a guideline for assessing the accessibility of specific facilities for individuals with disabilities. Refer to pages 915-919 in Dunn and Leitschuh's (2006) text as a reference to complete this form. (Possible 10 points each)

Name of Facility Garver Ground Floor Students Robin Stevenson Tyler Smith

1. Site

The facility (Garver) was easily accessible by foot, wheelchair and vehicle.

2. Parking

The parking provided on-site, clearly marked parking spaces for individuals with disabilities. There should probably be another ramp by the parking site to help adapt students with disabilities. There also needs to be more parking spaces, to help accommodate people with handicaps.

3. Access to Building

All walkways leading to the facility on ground level were easily accessible. The doors were wide enough.

4. Entrance to Building

The entrance to the building was not easily accessible, it took more than one effort (person) to help open the door. The doors were not automatically activated either. A wheelchair could not be seen through the other side of the door.

5. Ramps

The ramps were not easily accessible. It was easy to get onto ground floor. But the facility provided no ramps to help a student throughout the facility to get to the 1st, 2nd or 3rd floor. Ramps should be provided to help accommodate those with disabilities.

6. Stairs

Throughout the facility, there were stairs, but they were not easily accessible for students with disabilities. None of the stairs were seven inches or less and they were also not slanted. There were handrails provided but it was impossible to get up them with a wheelchair.

7. Elevators

Elevators were not easily accessible throughout the facility. There were no elevators in the whole facility.

8. Restrooms

The restrooms were easily accessible and the floors ^{were} level throughout. The door needed to be more accessible and wider to help those with disabilities. I think it'd be a good idea to have two doors there in the restroom. Also the stalls need to be wider and there needs to be a ramp to help get the person in the shower.

9. Water Fountains

The facility provided water fountains with up-front spouts and controls. The fountain could not be accessed by being operated by foot. The water fountains needed to be lowered to help accommodate those with disabilities.

10. Telephones